NU. DE COPIES RECEIVED DISTRIBUTION SANTA FE I FILE I V U.S.G.S. LAND OFFICE OPERATOR	NEW MEXICO OIL CONSERVATION COMMISSION	Form C-100 Supersedes Old C-102 and C-100 Effective 1-1-65 Sa. Indicate Type of Leise State Fee X 5. State Cil 5 Gas Leise No.
SUNDRY	NOTICES AND REPORTS ON WELLS SALS TO DRILL OR "O DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. FOR PERMIT - " (FORM C-1C1) FOR SUCH PROPERALS.	
		7, Unit Agreement Name
Aminoil USA, Inc.	OTHER- Drilling Well Active 2850	8. Farm of Lease Name Kirkes Comm
3. Adaress of Gerator P. O. Box 10525, Midland	d, Texas 79702	S. Well No.
4. Location of Well	30 FEET FROM THE South LINE AND 1773	10. Field and Pool, or Wildoat Undes. Malaga Morrow
	10 24S 28E	
	15. Elevation (Show whether DF, RT, CR, etc.) 3003' G.L.	12. County Eddy
Check Ap	propriate Box To Indicate Nature of Notice, Report	
NOTICE OF INT	ENTION TO: SUBSEC	UENT REPORT OF:
PERFORM REMEDIAL WORK	PLUS AND ABANDON REMEDIAL WORK Commence drilling opns. Change plans casing test and cement job	ALTERING CASING
OTHER	OT + ER	
17. Desprise Proposed or Completed Open work) SEE RULE 1103.	ations (Clearly state all pertinent details, and give pertinent dates, in	cluding estimated date of starting any proposed
	6' of 7-5/8", 39#, S-95, SFJ-P Hydril casi	ng liner to ll,998' as
Float Collar	1.85 asing, 39#, S-95, SFJ Hydril 78.69 1.29 asing, 39#, S-95, SFJ Hydril 2375.36 Liner Hanger <u>8.64</u>) 1) 1 ; 1
Total depth cas Top of liner ha	•	3.
Halad-22 and .4	35 sacks of Class "H" cement with 3/4 of 1 % CFR-2, and 2% HR-7 and 3 lbs. KCL per sa 0. WCC 25 hours.	
		OVER
18. I hereby certify that the information at	pove is true and complete to the best of my knowledge and belief.	
SIGNED _ Lerry A. F.F.	ange Operations Superinten	dentJuly_18, 1980
APPROVED BY UN, a, Are	SUPERVISOR, DISTRICT	M AUG 4 1980
CONDITIONS OF APPROVAL, IF ANY:		

		'		
CONDITIONS	OF	APPROVAL.	1F	ANY:

6-30-80 - Trip in hole with 8½" bit. Tag cement at 8893'. Drilling cement to top of 7-5/8" liner at 9532'. Fested liner lap to 1500 psi - 0.K.

•

7-3-80 - Pick up $6\frac{1}{2}$ " bit, trip in hole and clean out 7-5/8" liner to float shoe. Tested casing to 1500 psi - 0.K. Displaced hole with mud. Drilling ahead.