Lechuguilla Canyon Unit #. Page 3

## 10. PLANS FOR RESTORATION OF THE SURFACE.

- A. After finishing drilling and/or completion operations, all equipment and other material not needed for further operations will be removed. The location will be cleaned of all trash and junk to leave the wellsite in as aesthetically pleasing a condition as possible.
- B. Ungarded pits, if any, containing fluids will be fenced until they have been filled.
- C. If the proposed will is non-productive, all rehabilitation and/or vegetation requirements of the BLM and the USGS will be complied with and will be accomplished as expeditiously as possible. All pits will be filled leveled within 90 days after abandonment.
- 11. OTHER INFORAMTION.
  - A. Topography: The land surface in the vicinity of the wellsite is hilly, with deep arroyos and intermittent creeks. The immediate area of the wellsite is discussed above in paragraph 9B.
  - B. Flora and Fauna: The vegetation cover consists of , scrub juniper, sotol, and miscellaneous desert growth. Wildlife was observed, so the wildlife in the area probably includes those typical of semi-arid land. The area is used for cattle grazing.
  - C. There are no ponds and streams in the area. A windmill is located at NE 1/4 of Section 10, T24S R24E and water well west of Bill Smith mobile home.
  - D. There are inhabited dwellings in the vicinity of the proposed well. Bill Smith mobile home is 2 miles NW from location.
  - E. Surface Ownership: The wellsite is on federal surface with federal minerals.
  - F. There is no evidence of any archeological, historical or cultural sites in the immediate area of well site. See Archeological Report.
- 12. OPERATOR'S REPRESENTATIVE.
  - A. The field representative responsible for assuring compliance with the approval surface use plan are:

Gliserio "Rod" Rodriguez or Johnny A. Lopez Yates Petroleum Corporation 207 South 4th Street Artesia, New Mexico 88210 Phone: (505) 746-3558