

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐
2. NAME OF OPERATOR
Yates Petroleum Corporation ✓
3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1630' FSL & 2235' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>

(other) Drilling progress & running intermediate csg.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 3269' Lost circulation at 3247' & 3258'. Could not drill further efficiently; set various plugs without success, drilled to 3795' and rigged up to run 7" casing. TD 3795' Ran 94 joints of 7" 20# 8rd T&C casing set at 3795'. 1-Texas Pattern guide shoe at 3795'. Flapper float at 3775'. Cemented w/150 sacks Class C 2% CaCl. PD 3:30 AM 12-21-80. No cement was circulated. WOC 18 hours. Nippled up and tested to 800 psi, okay. Resumed drilling.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED John H. Hall TITLE Secretary DATE 2-18-81

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

5. LEASE	NM-12391-A
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	Serpentine Bends Unit
8. FARM OR LEASE NAME	Serpentine Bends Unit
9. WELL NO.	1
10. FIELD OR WILDCAT NAME	Wildcat
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	Unit K, Sec. 25-24S-23E
12. COUNTY OR PARISH	Eddy
13. STATE	NM
14. API NO.	
15. ELEVATIONS (SHOW DF, KDB, AND WD)	4517' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

ACCEPTED FOR RECORD

FEB 20 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

RECEIVED FOR RECORD

FEB 20 1981

ROBERT L. WILSON
U.S. GEOLOGICAL SURVEY