



No. 04434

P.O. Box 60527
Midland, Texas 79711
915/563-2805

RIG NO. 497
JOB NO. 044046

TIME SHEET

NAME OF COMPANY		WELL NAME & NO.	DATE
HALLWOOD PET.		COCHILLUM #1	5-10-84
NAME OF EMPLOYEE		HOURS	SAFETY REPORT
Operator	DAVID	6-1	NO ACCIDENTS
Helper			
Helper			
Helper			
Helper			

Day No. ROAD CREW TO LOC. RUN WIRELINE TRK R/HW/WL SHOOT 4-HOLES AT 500' POSHW/WL R/HW/TBG PUMP SUCKS CMT IN PERFS AT 500' LEAVE 100' CMT IN 2 5/8" CSG POSHW/TBG WATCH WELL FOR 1 1/2 HRS. FLUID LEVEL FALLING SHUT WELL IN TAG PLUG IN MORNING ROAD CREW TO MOTEL.

CEMENT	CLASS	SACKS		
SALT GEL		SACKS		
CALCIUM CHLORIDE		SACKS		
ELEV. BOWLS, SLIPS		SIZE		
PUMP CHARGES		HOURS		
HYDRAULIC JACKS		HOURS		
TUBING TONGS		SIZE		
CASING TONGS		SIZE		
BOP				
WATER TANKS		QTY.		
PULLING UNIT		HOURS		
TRAVEL TIME		HOURS		
OTE		DAYS		
SUPERVISOR EXP.		MILEAGE	MEALS & LODGING	
SUPERVISOR LABOR		DAYS		
CEMENT RETAINER		QTY.	SIZE	TYPE
CIBP		QTY.	SIZE	
W/L TRUCK		HOURS	STANDBY	
SETTING CHARGE		QTY.		
PERFORATING		QTY.	CSG. SIZE	
CASING CUTS		QTY.	DEPTH	
OTHER W/L SERVICES	DESC.			
PIT WORK	CONTRACTOR	HRS.	TKT. NO.	AMT.
WATER COST	CONTRACTOR	HRS.	TKT. NO.	AMT.
WELDING	CONTRACTOR	HRS.	TKT. NO.	AMT.
TRUCKING (HAUL TRUCK)	CONTRACTOR	HRS.	TKT. NO.	AMT.
TRUCKING (CEMENT)	CONTRACTOR	HRS.	TKT. NO.	AMT.
OTHER THIRD PARTY	ITEM/SERVICE		TKT. NO.	AMT.
	ITEM/SERVICE		TKT. NO.	AMT.
	ITEM/SERVICE		TKT. NO.	AMT.
	ITEM/SERVICE		TKT. NO.	AMT.

POOL SUPERVISOR <u>Ag WL</u>	DATE <u>5-10-84</u>
COMPANY REPRESENTATIVE _____	DATE _____