

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR

Amoco Production Company

3. ADDRESS OF OPERATOR

P. O. Box 68, Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1650' FWL X 1980' FNL

AT TOP PROD. INTERVAL: (Unit F, SE/4, SW/4)

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED
DEC 29 1981

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

5. LEASE

NM 16311

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

RECEIVED

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME DEC 31 1981

Federal AD Com.

9. WELL NO.

1

O. C. D.

ARTERIA, OFFICE

10. FIELD OR WILDCAT NAME

Wildcat Bone Springs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

3-23-28

12. COUNTY OR PARISH

Eddy

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3012.4' GL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved in service unit 12-14-81 (X-Pert #15). Perfed Bone Springs intervals 6288', 6284', 6280', and 6276' with 2 JSPF. Ran retrievable bridge plug set at 6350'. Tailpipe set at 6237' and packer set at 6202'. Acidized with 2000 gal. 15% HCL. Swabbed 16 hrs., recovered 43 BW. Pulled tubing, packer, and retrievable bridge plug. Ran 2-3/8" tailpipe, 7-5/8" packer, and 2-3/8 tubing, packer set at 6209' and tailpipe landed at 6242'. Moved out service unit 12-21-81.

0+6-USGS, R 1-Hou 1-Susp 1-W. Stafford, Hou 1-DMF 1-Union Oil
1-Read & Stevens 1-Holly

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

ROGER A. CHAPMAN

TITLE Ast. Adm. Analyst

DATE 12-23-81

(This space for Federal or State office use)

APPROVED BY

DEC 30 1981

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO