



# BEN JETT-CATHEY WIRE LINE SERVICE

P. O. BOX 787  
ARTESIA, NEW MEXICO 88210  
Phone (505) 746-3281



## BOTTOM HOLE PRESSURE SURVEY REPORT

OPERATOR READ & STEVENS  
LEASE KIMBERLY  
WELL NO. 1  
POOL                      FORMATION ATOKA  
DATE 6-22-85 TIME 1637  
CO. MAN DARRELL LOUDER  
STATUS SHUT IN TEST DEPTH 11080  
TIME S.I. 1415 HRS LAST TEST DATE                       
6-19-85 BHP LAST TEST                       
TUB. PRES. 5383.2 BHP CHANGE                       
CAS. PRES.                      FLUID TOP                       
DATUM PLANE                      WATER TOP                       
DATUM PSIA 6922.2 RUN BY STEVE SILVEIRA  
TEMP 195 CLOCK # B-3443  
PRESSURE RANGE 8600 #  
ELEMENT NO. RPG3#18323

| DEPTH | PSIA<br>PRESSURE | LBS/100 FT<br>GRADIENT |
|-------|------------------|------------------------|
| 0     | 5383.2           |                        |
| 3000  | 5827.2           | 14.8                   |
| 6000  | 6231.2           | 13.5                   |
| 9000  | 6606.2           | 12.5                   |
| 10000 | 6728.2           | 12.2                   |
| 10930 | 6843.2           | 12.4                   |
| 11080 | 6863.2           | 13.3                   |
| 11479 | 6922.2           | 14.7                   |

11479 FEET WAS EXTRAPOLATED

TIME B.H.P. MEASURED 1637 HOURS

LENGTH OF TIME WELL SHUT IN

74 HOURS 32 MINUTES

PERFORATIONS FROM 11157 TO 11801

