



# BENNETT-CATHEY WIRE LINE SERVICE

P. O. BOX 787

ARTESIA, NEW MEXICO 88210

Phone (505) 746-3281



## BOTTOM HOLE PRESSURE SURVEY REPORT

**OPERATOR** READ & STEVENS  
**LEASE** KIMBLEY  
**WELL NO.** 1  
**POOL** FORMATION ATOKA  
**DATE** 7-11-86 **TIME** 1258 HOURS  
**CO. MAN** JOE HANDLEY  
**STATUS** SHUT IN **TEST DEPTH** 11090'  
**TIME S.I.** 1115 HRS **LAST TEST DATE** 7-8-86  
**BHP LAST TEST** \_\_\_\_\_  
**TUB. PRES.** 3928.2 **BHP CHANGE** \_\_\_\_\_  
**CAS. PRES.** \_\_\_\_\_ **FLUID TOP** \_\_\_\_\_  
**DATUM PLANE** \_\_\_\_\_ **WATER TOP** \_\_\_\_\_  
**DATUM PSIA** 5216.2 **RUN BY** BO FAULKENBERRY  
**TEMP** 240° **CLOCK #** B-3443  
**PRESSURE RANGE** 5025#  
**ELEMENT NO.** RPG3#23914

DEPTH	PSIA PRESSURE	LBS/100 FT GRADIENT
0	3938.2	
3000	4283.2	11.5
6000	4626.2	11.4
9000	4950.2	10.8
10940	5147.2	10.2
11090	5166.2	12.6
11479	5216.2	12.8

11479 FEET WAS EXTRAPOLATED  
 TIME B.H.P. MEASURED 1258 HOURS  
 LENGTH OF TIME WELL SHUT IN  
 73 HOURS 43 MINUTES  
 PERFORATIONS FROM 11157 TO 11801

