OIL CONSERVATION DIVISION DISTRICT II ARTESIA 811 3. FIRST ST. ARTESIA, NM 88210 (503) 748-1283 FAX (505) 748-0720

Jennifer A	. Salisbury	December	27, 1999		
Ram Energy Inc					
601 N. Marienfeld, Ste 102					
Midland, TX 79701					
·	gging Reports		Lease		Ut S-T-R
Form C-103 Report of Plugging for your Brantley Com #1 M-23-23S-28E cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been done and location is ready for final inspection.					
( ) 1.	All pits have been filled and leveled.				
( ) 2.	Rat hole and cellar have been filled and leveled.				
( ) 3.	level has been set in concrete to mark the exact location of plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)				
( ) 4.	The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.				
( ) 5.	The dead men and tie downs have been out and removed.				
( ) 6.	and least remaining well on lease, the battery and				
The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.					
When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.					
I certify that the above work has been done and the above mentioned lease is ready for OCD inspection and approval.					
Name				miko Stub Mike Stub Field Rep	ble¥ield

Title