

WELL NAME AND NUMBER Pure Gold "C" Federal #1
LOCATION Section 17, T23S, R31E, Eddy County, New Mexico
OPERATOR Coquina Oil Corporation
DRILLING CONTRACTOR Bilmar Drilling, Inc.

The undersigned hereby certifies that the following deviation tests were conducted by the contractor and reported to the operator with the following results:

<u>Degrees @ Depth</u>	<u>Degrees @ Depth</u>	<u>Degrees @ Depth</u>	<u>Degrees @ Depth</u>
<u>1° @ 250'</u>	<u>3/4° @ 1880'</u>	<u>3/4° @ 4560'</u>	<u>1° @ 8576'</u>
<u>1/2° @ 386'</u>	<u>3/4° @ 2130'</u>	<u>1° @ 4787'</u>	<u>1 1/2° @ 9094'</u>
<u>1 1/2° @ 606'</u>	<u>3/4° @ 2220'</u>	<u>1° @ 5026'</u>	<u>1 1/2° @ 9342'</u>
<u>2° @ 673'</u>	<u>1/4° @ 2653'</u>	<u>1° @ 5240'</u>	<u>1 1/2° @ 9564'</u>
<u>2 1/2° @ 726'</u>	<u>1/4° @ 2721'</u>	<u>1° @ 5493'</u>	<u>1 1/2° @ 9977'</u>
<u>1 1/2° @ 799'</u>	<u>1/2° @ 2804'</u>	<u>1° @ 5706'</u>	<u>2 1/4° @ 10,349'</u>
<u>1-3/4° @ 861'</u>	<u>1/2° @ 2856'</u>	<u>1 1/4° @ 5924'</u>	<u>2° @ 10,412'</u>
<u>1 1/4° @ 931'</u>	<u>3/4° @ 3040'</u>	<u>1° @ 6174'</u>	<u>2° @ 10,513'</u>
<u>1 1/2° @ 994'</u>	<u>1° @ 3194'</u>	<u>3/4° @ 6229'</u>	<u>3° @ 10,700'</u>
<u>1° @ 1056'</u>	<u>1° @ 3400'</u>	<u>3/4° @ 6505'</u>	<u>2° @ 10,780'</u>
<u>1° @ 1137'</u>	<u>2° @ 3600'</u>	<u>1° @ 6785'</u>	<u>2° @ 10,874'</u>
<u>3/4° @ 1222'</u>	<u>1 1/4° @ 3700'</u>	<u>1/4° @ 7020'</u>	<u>2° @ 11,065'</u>
<u>1/2° @ 1316'</u>	<u>1 1/2° @ 3800'</u>	<u>1/2° @ 7236'</u>	<u>1-3/4° @ 11,427'</u>
<u>0° @ 1480'</u>	<u>1° @ 3916'</u>	<u>3/4° @ 7329'</u>	<u>1° @ 11,851'</u>
<u>1° @ 1658'</u>	<u>3/4° @ 4110'</u>	<u>1 1/4° @ 7820'</u>	<u>1/4° @ 12,597'</u>
<u>3/4° @ 1732'</u>	<u>1° @ 4310'</u>	<u>3/4° @ 8357'</u>	<u>3/4° @ 13,277'</u>