

Pardue "19" #1
I, 19, 24-S, 28-E
Eddy Co., New Mexico

- 1-29-82 9 hrs NU BOP's. PU BHA & WIH. Tested BOP's & csg to 600 psi for ½ hrs.
Tested OK. Drilled float collar, cmt & float shoe.
- 1-30-82 Drilled to 1035'.

C. H. A.
2-1-82