

InterNorth, Inc.

WELL NAME AND NUMBER:

Pardue "19" Com. #1

COUNTY:

Eddy

STATE: New Mexico

OPERATOR ----- WELL	DEPTH	STATUS OF OPERATIONS
VI-PARDUE "19" COM. #1 1980' FWL & 660' FEL SEC 19, T-24-S, R-28-E EDDY COUNTY, NEW MEXICO ELEV: 3078.6' GL #101-09 MALAGA 000' MORROW (WC) INI & NORTEX %: BPO: INI 30.11107% WI 24.46525% NRI BPO: NORTEX 11.31485% WI 8.48610% NRI APO: INI SAME APO: NORTEX 6.84235% WI 5.13176% NRI GAS CALL: INI & NORTEX HAS A CALL ON W.I. SHARE	12,900' TD	5-28-82 Ran Otis WL & equalize press under pkr Unable to remove plug & pkr. RD Otis. Pull 302 jts 2-7/8" tbg. SDON 5-29-82 thru 6-1-82 Remove pkr, WIH w/tbg scraper & bit. Displac mud w/9-9.6# BW. Pull 2 jts tbg. SI for Sunday & Monday. 6-2-82 POH w/tbg, scraper & bit. LD scraper & bit WIH w/Otis 5" Permalatch pkr. Set @ original setting. TOP @ 12,282'. RU Otis WL. Set 2 way plug & tst. POH w/WL. Unseat tbg from pkr. LD 11 jts, 341' tbg. 40 jts dn on rack. 6-3-82 POH w/tbg. RU Otis & ran M H 5" pkr w/393 jts 2 7/8" tbg. Install Cameron Christmas tree & tst. SDFN. Prep to perf Atoka. 6-4-82 RU Gearhart prep to perf Atoka. Ran GR Correlation log. RIH w/perf gun. Perf 12,092½-95', 12,099-103', 12,174-78' 4 sh/ft, 16 holes, gun failed. POH & check failure. Found moisture in gun. WL spooling devise broke out of mount. Welded, RD Gearhart for repairs. Will resume 8 am. 6-5-82 SITP 200 psi. RU Gearhart. Perf 12092½-95' & 12009-103'. No inc in press. POH & RD Gearhart. RU & swab 6 runs-very slight show of gas. Rec 78 BW. SDFN. 6-6-82 11 hr SITP 400 psi. Swab wtr w/gas inc slightly after each run. Made 15 swab runs. Rec 185 BW w/FL remaining @ 3000'. Gas enough for continous burn. SDFN. 6-7-82 SI for Sunday.