

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYNEW MEXICO OIL CONS. COMMISSION
Order DD
Artesia, NM 88210

5.1 E

NM-19593

c/sf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR

Mesa Petroleum Co.

3. ADDRESS OF OPERATOR

P.O. Box 2009 / Amarillo, Texas 79189

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1650' FNL & 1650' FWL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON* ☐

(other) Spud, 16" Csg & Cement

SUBSEQUENT REPORT OF:

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded well with 20" hole on 9-24-82. Drilled to 250' and ran 6 jts 16", 65#, H40 Casing set at 250'. Cemented with 200 SX "c" + 1% CaCl + 1/2% Celloflakes and tailed in with 200 SX "c" + 1% CaCl. PD at 10:00 p.m. 9-25-82. Circulated 50 SX. Drilled ahead on 9-26-82. WOC total of 22 hours.

XC: MMS (3), TLS, CEN RCDS, ACCTG, REM (FILE), MIDLAND, HOBBS, PARTNERS ()

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

REGULATORY
COORDINATOR

SIGNED

R. E. Mark

TITLE

DATE

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

OCT 5 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See Instructions on Reverse Side

RECEIVED
SEP 28 1982OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO