STATE OF NEW MEXICO	2.1 ²		
ENERGY AND MINERALS DEPARTMENT	OIL CONSERVA	THON DIVISION	
DISTRIBUTION			f Form 5 100
JANTA FE	P.O.BO		Forn C-103 Revised 10-1
FILE VIL	SANTA FE, NEW	MEXICO 87501	
U.S.G.S.			Sa. Indicate Type of Leuse
LAND OFFICE		DEC 8 1982	State X Foe
OPERATO.			5. State Oll & Gas Leave No.
		O. C. D.	LG-467
	NOTICES AND REPORTS ON	WELLS ARTESIA, OFFICE	MINININ (MARKA)
1. OIL GAS X	0TH [11-		7. Unit Agreement Nume
2. Name of Operator			8. Farm or Lease Name
Amoco Production Company			State "DS" Gas Com
3. Address of Operator			9. Well No.
P. O. Box 68, Hobbs, New Mexico 88240			1
4. Location of Well	· · · · · · · · · · · · · · · · · · ·		10. Field and Pool, or Wildcat
UNIT LETTER	980 South	1980 LINE AND FEET FRO	Und. Wolfcamp
THEEast LINC, SECTION	3423-S	27-E	
	15. Elovation (Show whether 3171.3 GL		12. County Eddy
Check A	ppropriate Box To Indicate N rention to:		ther Data
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORAHILY AJANDON		COMMENCE DRILLING OPHS.	
PULL OR ALTER CASING	CHANGE PLANS		PLUG AND ABANDONMENT
		CASING TEST AND CEMENT JOB	
OTHER	[]	OTHER <u>Change Zones</u>	
17. Describe Proposed or Completed Oper work) SEE RULE 1903.	ations (Clearly state all pertinent dete	nils, and give pertinent dates, includin	g estimated date of starting any prope
tubing, packer, and Var	Killed well and install nn gun assembly. Ran 4-	1/2" cast iron bridge p	lug and set at 11.093.
Pressure tested to 1,00	00 psi-OK. Capped with	45 sx class H cement.	Pulled up to 10,250'

and spot 6 bbl 10% acetic acid from 10,250'-9850'. Ran bit and cleaned hole. Tagged cement at 10,468'. Ran tailpipe, packer, and tubing. Tailpipe landed at 9938' and packer landed at 8736'. Pressure tested packer to 1000 psi for 15 min. Held OK. Ran 1-9/16" thru tubing gun and perforated intervals 10,040'-50', T0205'-13' and 10,219'-24' with 4 JSPF for a 92 hole total. Swabbed 9 hr. and recovered apx. 56 BLW and slight show of gas. Acidized with 4000 gals 20% NEFE HCL acid with additives and 150 ball sealers. Tagged with RA material. Opened well and recovered 110 BLW. Well started to flow. Flowed 4 hrs. and recovered 1 BLW with 15'-18' flare. MOSU and installed test equipment. Flow tested 144 hr. and recovered 19 BLW and 875 MCF. Shut-in well for bottom hole pressure test. Currently evaluating results of BHP test.

0+4-NMOCD,A 1-HOU 1-CMH 1-W	. Stafford, HOU	
id. I hereby consider that the information above in true and o	complete to the best of my knowledge and belief.	
(Karbs m. Verrin	Assist. Admin. Analyst	12-6-82
Original Signed By Leslie A. Clements Supervisor District II CONDITIONS OF APPROVAL, IF ANY:	TITLE	DEC Q 1082