



KUYKENDALL
Bottom Hole Pressure Service Company
P.O. Box 11296 / A/C 915-337-5241 / Odessa, Texas 79760

BOTTOM HOLE PRESSURE REPORT

Operator Casquina Oil Corp. Lease Craft Well No. 1
Field South East Malaga Reservoir Atoka Datum MP 11,876
Test Date 9-29-82 Well Status Shut In Hours Shut In 136
Tubing 2-7/8 Depth _____ End _____ Packer 11,808 S. N. 11,807
Casing _____ Depth _____ Perf. 11,868 - 11,884 Total Depth _____

	Depth	Press. Lbs/Sq. In.	Δ Press.	Gradient Lbs/Ft.
Tubing Press. <u>4,887</u>	0	4,887		
Casing Press. _____	3,000	5,211	324	.106
Top of Fluid. <u>NONE</u>	6,000	5,529	318	.106
Top of Water. _____	9,000	5,850	321	.107
Temp. @ _____ °F.	11,500	6,115	265	.106
Elev. KB. _____ Gl.	11,830	6,150	35	.106
Last Test Date. _____				
Press. Last Test. _____				
Change. _____ Per Day. _____				
Inst. No. <u>34516</u> Cal. <u>6-81</u>	<u>-46</u>	<u>+5</u>		
Tested By. <u>Fyle</u>	<u>-11,875</u>	<u>-6,155</u>	(Mid Perf)	(.106)
Calcu. By. <u>Spruell</u>				
Prod. Index. _____ Bbls/day/lb.				
Drop. _____				
Cumulative prod. _____				

Remarks: