

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other

RECEIVED

2. NAME OF OPERATOR

PENNZOIL COMPANY ✓

OCT 14 1982

3. ADDRESS OF OPERATOR

P.O. Drawer 1828, Midland, TX 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1650' FNL & 1650' FWL of sec.

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH: 21, T24S, R26E

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Perforate & Complete

5. LEASE

L C 065347

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

EDDY - 21 - Federal Com.

9. WELL NO.

#1

10. FIELD OR WILDCAT NAME

White City Penn Gas

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 21, T24S, R26E

12. COUNTY OR PARISH

EDDY

13. STATE

N.M.

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3373.4 GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

1982

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

08-20-82:TD 11503'-PBTD 11429,Moved in completion unit.

08-21-82:Displaced hole with 2% KCL water-spot 300 gals,71/2% HCL from 11430' to 10970'.

08-22-82:Ran tubing to 10992' & set backer w/15000# weight.

08-23-82:Nipple up tree & perforate 1 shot per ft.(37 holes)at 11048,51, 53,54,95,96,99- 11,100 ,02,03,04,05,06,07,26,27,28,29,91,92,93, 94,96,97-11208,09,10,11,29,30,31,32-11404,05,07,08,09-shut well in

08-26-82:SITP 1550#-Acidized Morrow perf.W/7500 gals of 71/2% HCL.

08-27,28,29-82: Testing well.

08-30-82:Shut well in for 72hr. Pressure build up.

09-07-82:Ran 4 PT test. CAOF of 1067 MCFPD.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

ACCEPTED FOR RECORD

TITLE

Oper. Engr.

DATE

09/08/82

(ORIG. SGD.) DAVID R. GLASS

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL

OCT 12 1982

TITLE

DATE

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See Instructions on Reverse Side