ENERGY AND MINERALS DEPARTMENT DISTRIBUTION BANTA FE SANTA FE	Form C-103 · Revised 10-1-78
C. D. U.S.O.S. LAND OFFICE	Sa. Indicate Type of Leuse State XX Fee
DPERATOR	LG-468
SUNDRY NOTICES AND REPORTS ON WELLS	7. Unit Agreement Name
3. •1L X GAB 0THER.	
2. Nome of Operator The Desana Corporation	8, Farm or Lease Home Amoco MU State
3. Address of Coverator 600 Bldg. of the Southwest, Midland, Texas 79701	9. Well No. 1-Y
4. Location of Well WHIT LETTERJ 1980 FEET FROM THE South LINE AND 1950 FE	10. Field and Pool, or Wildcat Wildcat Delaware Sand
THEEast LINE, BECTION 6 TOWNSHIP 24-S RANCE 27-E	
15. Elevation (Show whether DF, RT, CR, etc.) 3241.9 GL	12. County Eddy
16. Check Appropriate Box To Indicate Nature of Notice, Report NOTICE OF INTENTION TO: SUBSEC	or Other Data QUENT REPORT OF:
PERFORM REMEDIAL WORK PLUE AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPHS.	ALTERING CASING ALTERING AND ADANDONMENT X
PULL OR ALTER CABING	
отися	reluding estimated date of starting any proposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was plugged and abandoned as follows:

Hole was circ w/10.2 ppg salt gel laden brine from 1995'. CIBP was set @ 1950' and capped w/35' cmt. 4½" csg was cut @ 1608' and pulled out of hole. Tbg was run to 1650' and a 90 sx Class "C" cmt plug was pmp. WOC 3 hrs. Tagged top of plug @ 1550'. Set 60 sx cmt plug @ 570'. WOC. Tagged top of plug @ 467'. Set 10 sx cmt plug @ 30'. Circ cmt to surface.

8-5/8" csg head was cut off. Plate was welded on 8-5/8" csg & dry hole marker installed. Well was P&A 3/11/84.

Pmp Unit & Tank Batt was moved off location. Location was cleaned up and is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

 Tom R. Cook	TITLE	Agen

Barr	Brook	
CONDITIONS OF APPROVAL.		

4/23/84