

**FEB 23 1983**

Form 9-331  
 Dec. 1973

Form Approved.  
 Budget Bureau No. 42-R1424

UNITED STATES  
 DEPARTMENT OF THE INTERIOR  
 GEOLOGICAL SURVEY

O. C. D.  
 ARTESIA, OFFICE

5. LEASE  
 NM 0554481

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
 Union Federal

9. WELL NO.  
 2

10. FIELD OR WILDCAT NAME  
 Esperanza Delaware

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
 Sec. 11-22S-27E

12. COUNTY OR PARISH | 13. STATE  
 Eddy | N.M.

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
 3101' GR

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well  gas well  other

2. NAME OF OPERATOR  
 Marbob Energy Corporation ✓

3. ADDRESS OF OPERATOR  
 P.O. Dr. 217, Artesia, N.M. 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
 AT SURFACE: 1650 FNL 330 FWL  
 AT TOP PROD. INTERVAL: Same  
 AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

|                          |                          |                                     |
|--------------------------|--------------------------|-------------------------------------|
| REQUEST FOR APPROVAL TO: |                          | SUBSEQUENT REPORT OF:               |
| TEST WATER SHUT-OFF      | <input type="checkbox"/> | <input type="checkbox"/>            |
| FRACTURE TREAT           | <input type="checkbox"/> | <input type="checkbox"/>            |
| SHOOT OR ACIDIZE         | <input type="checkbox"/> | <input type="checkbox"/>            |
| REPAIR WELL              | <input type="checkbox"/> | <input type="checkbox"/>            |
| PULL OR ALTER CASING     | <input type="checkbox"/> | <input type="checkbox"/>            |
| MULTIPLE COMPLETE        | <input type="checkbox"/> | <input type="checkbox"/>            |
| CHANGE ZONES             | <input type="checkbox"/> | <input type="checkbox"/>            |
| ABANDON*                 | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| (other)                  |                          |                                     |

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well was TD at 4725' on 12/24/82. No commercial production was encountered and well was plugged and abandoned as follows: We set a 100' plug at 2080-2180', a 100' plug at 680-780', a 100' plug at 425-525' in and out of the 8 5/8" casing, and a 15 sack plug at surface. A dry hole marker will be set and location cleaned as soon as the weather permits.

**RECEIVED**

JAN 3 1983

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_

OIL & GAS  
 MINERALS SECTION  
 ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Carolyn Orris TITLE Production Clerk DATE 12/30/82

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
 CONDITIONS OF APPROVAL, IF ANY: