

c/sf

NM OIL CONS. COMMISSION

 Drawer DD
 Artesia, NM 88210

RECEIVED BY

MAY 20 1985

 Form 9-331
 Dec. 1973

 Form Approved.
 Budget Bureau No. 42-R1424

 O. G. UNITED STATES
 ARTESIA OFFICE
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR
Marbob Energy Corporation ✓
3. ADDRESS OF OPERATOR
P.O. Dr. 217, Artesia, N.M. 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
 AT SURFACE: 1650 FNL 330 FWL
 AT TOP PROD. INTERVAL: Same
 AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

 TEST WATER SHUT-OFF ☐
 FRACTURE TREAT ☐
 SHOOT OR ACIDIZE ☐
 REPAIR WELL ☐
 PULL OR ALTER CASING ☐
 MULTIPLE COMPLETE ☐
 CHANGE ZONES ☐
 ABANDON* ☐
 (other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☒

5. LEASE
NM 0554481
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Union Federal
9. WELL NO.
2
10. FIELD OR WILDCAT NAME
Esperanza Delaware
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 11-22S-27E
12. COUNTY OR PARISH
Eddy
13. STATE
N.M.
14. API NO.
30-01S-24343
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3101' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well was TD at 4725' on 12/24/82. No commercial production was encountered and well was plugged and abandoned as follows: We set a 100' plug at 2080-2180', a 100' plug at 680-780', a 100' plug at 425-525' in and out of the 8 5/8" casing, and a 15 sack plug at surface. A dry hole marker will be set and location cleaned as soon as the weather permits.

RECEIVED

JAN 3 1983

Subsurface Safety Valve: Manu. and Type

 MINERALS SERVICE
 ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

 SIGNED Carolyn Davis TITLE Production Clerk DATE 12/30/82

(This space for Federal or State office use)

 APPROVED BY _____ TITLE _____
 CONDITIONS OF APPROVAL, IF ANY:

DATE

5-17-85

 ID-2
 5-24-85
 Y+H