

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
well well

2. NAME OF OPERATOR

BELCO PETROLEUM CORPORATION ✓

3. ADDRESS OF OPERATOR

411 PETROLEUM BUILDING MIDLAND, TX 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FWL & 100' FSL, Sec 6

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH: 600' FNL & 1980' FWL, Sec 7 ?

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

☐

FRACTURE TREAT ☐

☐

SHOOT OR ACIDIZE ☐

☐

REPAIR WELL ☐

☐

PULL OR ALTER CASING ☐

☐

MULTIPLE COMPLETE ☐

☐

CHANGE ZONES ☐

☐

ABANDON* ☐

☐

(other) CASING REPORT ☐

☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Ran 93 jts 13 3/8" K55 STC casing, set @ 3930'. Cemented w/ 4150 sx HLW + 1/4#/sx Flocele + 10#/sx salt. Mixed @ 12.8#/gal(1.88). Tailed in w/ 300 sx Class C + 0.5% CFR + 0.4 HALAD 22-A 3#/sx KCl. Mixed @ 15.7#/gal (1.2). Plug down @ 2:45 PM MST. Circ 185 sx cmt to surface.

RECEIVED

APR 29 1983

OIL & GAS

Set @

FL

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

ROSWELL, NEW MEXICO

SIGNED Rebecca J. Choi

TITLE Receptionist

DATE 4-28-83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

RJP

JUL 6 1983

*See Instructions on Reverse Side

ROSWELL, NEW MEXICO