CUSTOMER : BELCO/RESOURCE DRLG. CO.

WELL # : JAMES RANCH Unit NO. 14

LOCATION : EDDY CO., NEW MEXICO

DATE : 5-09-83, 5-09-83, 6-02-83, 7-12-83

JOB TYPE : GYRO, MMS, MMS, MMS

JOB # : GS1209, MS1210, MS1223, MS1233

SURVEYOR : ALAN HARBERT

DEPTHS : 0-3900, 3900-8380, 8380-11729, 11729-14623

DECL. : 10 DEGREES EAST

ELEV. : 0'

FILE # : WT-A6CS FROM WT-A3S:D701

METHOD : RADIUS OF CURVATURE

SECTION : 180

THIS SURVEY IS CORRECT TO THE BEST OF MY KNOWLEDGE AND IS SUPPORTED BY ACTUAL FIELD DATA.

D. Harbert

COMPANY REPRESENTATIVE

FINAL STATION DATA!

MEASURED DEPTH FEET	INCL. ANGLE DEGS.	HOLE DIRECTION DEGS.	COURSE LENGTH FEET	TRUE VERTICAL DEPTH FEET	VERTICAL SECTION FEET	RECTANGULAR COORDINATES N/S feet	E/W	CLOSURE DISTANCE FEET	DIRECTION DEGS.	DOG-LEG SEVERITY DG/100FT
[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]