

Dakota Resources, Inc. (I)
New Mexico State DU #1 SWD
Herradura (Delaware) Field

Pull plug from profile nipple. SITP = 800 psi. Flow well to pit overnight. Ru Watson Pump Truck. Run Casing Integrity test as per Ray Smith. Hold 300 psi for 30 minutes. No leakoff. Rd Lucky Well Service. Put well back into service @ 1800 hrs 5-18-96. SITP = 700 psi. Work Completed.