

C/87

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

RECEIVED

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐  
well well

## 2. NAME OF OPERATOR

Exxon Corporation

## 3. ADDRESS OF OPERATOR

P.O. Box 1600, Midland, Texas 79702

## 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 2310' FNL &amp; 2240' FEL of Sec.

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

## 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐

## SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐(other) Set casing

RECEIVED BY

MAY 11 1984

O. C. D.

ARTESIA, OFFICE

NOTE: Report results of multiple completion or zone change on Form 9-330.)

## 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1-7-84 Ran 5 1/2" 17# K-55 csg., set @ 5172'. DV tool @ 3020'. Cement 1st stage w/550 sx Class C & 2nd stage w/900 sx Class C. 1st stage circ., 2nd stage did not circ. Ran Temp. survey - TOC 1050'. Surface csg. set @ 1326'. WOC, csg. to be tested before completion begins.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

## 18. I hereby certify that the foregoing is true and correct

SIGNED

Malba Knippling

TITLE

Unit Head

DATE

January 17, 1984

ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY

GW

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY

MAY 9 1984

Carlsbad,

NEW MEXICO

\*See Instructions on Reverse Side