

CAL-MON #3

1980' FNL & 2180' FWL
SEC. 35 T-23-S, R-31-E
EDDY CO, NEW MEXICO

PAGE 2

8/30/85 - Continued

4 1/2 Hrs. RIH, PU 6-6 1/4" DC
1/2 Hr. Test pipe rams to 1000#, ok
1 Hr. Drl on plug