Rotary Engineers Laboratory, Inc.

CORE ANALYSIS MIDLAND, TEXAS CORE ANALYSIS

COMPANY	Pogo Producing Company	DEPTH	FROM 6057 TO 6098
WELL	Cal-Mon #3	DATE:	9-6-85
FIELD	Sand Dunes	ANALYST	DRM
FORMATION	Cherry Canyon	DRILLING FLUID	
COUNTY	Eddy	ELEVATION	KB 3494'; GL 3483'
STATE	New Mexico	LOCATION	2180' FWL, 1980' FNL, Sec. 35, 23 South, 31 East, Eddy County, New Mexico