

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT NM OIL CONS. COMMISSION

Form approved, 0151  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM 36610-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Robinia Draw W.I. Unit

8. FARM OR LEASE NAME

Fast Draw Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

section 5, T23S, R24E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry

2. NAME OF OPERATOR

W. A. Moncrief, Jr. ✓

3. ADDRESS OF OPERATOR

400 Metro Bldg., Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

2130' FNL & 660' FEL section 5, T23S, R24E

14. PERMIT NO.

30-015-26145

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

4153 Gd, 4166 KB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)

- (1) The well was drilled to 10,725' driller's depth and open hole logs were run by HLS on 8/22/89. HLS found T.D. of 10,726'.
- (2) Seven drill stem tests indicated all potential zones to be tight and impermeable. These tests are specifically described in detail on form 3160-4.
- (3) Operator set 6 cement plugs as follows on 8/23/89 & 8/24/89.  
Plug #1 10,050'-9,900' (150') 55 sax  
Plug #2 7,725'-7,625' (100') 45 sax  
Plug #3 4,725'-4,625' (100') 40 sax  
Plug #4 2,400'-2,300' (100') 45 sax. Plug was tagged at 2300' w/D.P.  
Plug #5 450'- 350' (100') 35 sax  
Plug #6 surface - 50' ( 50') 15 sax  
Plugging was witnessed by BLM representative Jim Amos.
- (4) Set dry hole marker on 8/24/89.

18. I hereby certify that the foregoing is true and correct

SIGNED Deputy E. Sharpton

TITLE Exploration Manager

DATE 8/28/89

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) DAVID R. GLASS

TITLE

DATE 8-31-89

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side