

BLM	
Land Office	
B of M	
Operator	

clsf
op +

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JUN 22 '90

WELL API NO. 30-015-26334
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Sidewinder
8. Well No. 1
9. Pool name or Wildcat Und. Crooked Creed (Morrow)

Section 20	Township 24-S	Range 24-E	NMPM	EDDY	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4277.6 GR					

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Yates Energy Corporation
3. Address of Operator P. O. Box 2323, Roswell, NM 88202-2323	4. Well Location Unit Letter F : 2310 Feet From The North Line and 1980 Feet From The West Line

Section 20	Township 24-S	Range 24-E	NMPM	EDDY	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4277.6 GR					

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-25-90 Drilled a 12 1/2" hole to 2460' KB. Ran 57 jts. 8 5/8" J-55 ST&C casing set @ 2460' KB. The hole was circulated for 20 minutes and cemented as follows:
Pumped 10 bbls. fresh water.
Cemented w/1000 sxs. Lite w/3% CACL2, 1/4# flocele/sx., and 10# gilsonite/sx.
Tailed in w/250 sxs. Class "C" w/2% CACL2.
Drop plug.
Displace with 154 bbls. fresh wtr.
Plug down @ 5:10 PM on 5-25-90.
Circulated 430 sxs. cmt. to surface.
Waited on cmt. 24 hours.

5-26-90 Resumed drlg. a 7 7/8" hole.

5-31-90 Safety test 3,000# BOP and manifold, 1500 psig on Hydrill, held ok. Drilling ahead.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sharon R. Hamilton TITLE Landman DATE 6-20-90

TYPE OR PRINT NAME Sharon R. Hamilton TELEPHONE NO. 623-4935

(This space for State Use) ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II
APPROVED BY _____ TITLE _____ DATE JUN 26 1990

CONDITIONS OF APPROVAL, IF ANY: