

WELL NAME & NUMBER Carrasco #14-5

LOCATION Eddy County, New Mexico

(Give Unit, Section, Township and Range)

OPERATOR R.B. Operating 2412 N. Grandview Suite 201 Odessa, TX 79761

DRILLING CONTRACTOR      Grace Drilling Company      9009 W. County Rd      Odessa, TX      79764

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above-described well and that he has conducted deviation tests and obtained the following results:

DEGREES @ DEPTH

## DEGREES @ DEPTH

## DEGREES @ DEPTH

DEGREES @ DEPTH

0.75 - 235

1.75 - 2507

2.00 - 565

1.75 - 2630

2.25 - 666

1.00 - 2783

2.00 - 758

1.00 - 2999

1.50 - 914

0.75 - .3489

1.75 - 1070

0.75 - 3950

1.00 - 1222

0.75 - 4445

1.00 - 1375

1.00 - 4820

1.00 - 1527

1.25 - 9321

0.75 - 1680

1.25 - 5812

0.75 - 1835

1.75 - 6310

1.50 - 1988

1.75 - 2138

2.50 - 2292

3.00 - 2415

Drilling Contractor      Grace Drilling Company

By K. Hauer

Subscribed and sworn to before me this \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_

Notary Public

My Commission Expires \_\_\_\_\_

County \_\_\_\_\_