

RECEIVED

WELL NAME & NUMBER South Culebra Bluff #23-12LOCATION Eddy County, New Mexico
(Give Unit, Section, Township and Range)

JUL 18 '90

OPERATOR R.B. Operating 2412 Grandview Suite 201 Odessa, TX 79761O. D.
ARTESIAN SPRINGDRILLING CONTRACTOR Grace Drilling Company 9009 W. County Rd Odessa, TX 79764

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above-described well and that he has conducted deviation tests and obtained the following results:

DEGREES @ DEPTH	DEGREES @ DEPTH	DEGREES @ DEPTH	DEGREES @ DEPTH
0.25 - 264	2.00 - 2518		
1.00 - 742	1.50 - 2610		
0.75 - 891	1.50 - 2762		
0.75 - 1052	1.00 - 2884		
0.75 - 1205	1.00 - 3162		
0.50 - 1361	0.75 - 3655		
1.00 - 1514	0.50 - 4046		
1.00 - 1666	0.50 - 4547		
0.50 - 1818	0.75 - 5033		
1.50 - 1969	1.00 - 5526		
1.75 - 2061	0.75 - 5790		
1.50 - 2152	1.00 - 6257		
2.00 - 2243	1.50 - 6350		
2.50 - 2335			
2.00 - 2425			

Drilling Contractor Grace Drilling CompanyBy *[Signature]*

Subscribed and sworn to before me this _____ day of _____, 19____

Notary Public _____

My Commission Expires _____

County _____