

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

SEP 28 '90

WELL API NO. 30-015-36382
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-120
7. Lease Name or Unit Agreement Name Medano VA State
8. Well No. 2
9. Pool name or Wildcat Und. W. Sand Dunes Morrow
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3345' GR

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line
Section 16 Township 23S Range 31E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Set liner, perforate, squeeze <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
7-12-90. Drilled DV tool at 7928'
TD 14886'. Reached TD 8-20-90. Ran 88 joints 4-1/2" 13.5# P110 liner set 11384-14886'.
Float shoe set 14886', float collar set 14843', landing collar set 14802'. Cemented w/450 sx
Class H w/2#/sx CSE, .4% CF-2, 1% CF-14, 1/2#/sx Hiseal (yield 1.28, wt 15.1). PD 12:30 AM
8-24-90. Bumped plug to 2200 psi for 2 minutes, held okay. No returns during cement job.
Perforated liner at 14270-14272' (4 holes), 11500-11502' (4 holes). No gain or loss of mud.
Set retainer at 11680'. Established circulation through cement retainer. Cemented w/375 sx
Class H + additives. Pressure tested to 500 psi, held okay. Drilled cement and retainer
11400-11471'. Tagged up at 11783'. Drilled cement 14118-14120'. Ran CBL, tool would not go
past 14222'. Tagged bottom at 14780'(wireline).
9-14-90. Perforated Morrow 14352-14363', 14389-14402' (4 JSPF)
9-22-90. Squeezed perms 14352-14402' to 6300 psi w/150 sx Class H + additives.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 9-28-90

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE OCT 4 1990

CONDITIONS OF APPROVAL, IF ANY: