TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON*

(other) Drill & Casing Settings

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE NM32636 6. IF INDIAN, ALLOTTEE OR TRIBE NAME NA	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME NA	
1. Oil GER Bas ADD 1 0 1001	8. FARM OR LEASE NAME Amoco "11" Federal	
well well other APR 1 6 1991	9. WELL NO. 5	
2. NAME OF OPERATOR RB Operating Company 3. ADDRESS OF OPERATOR ARTESIA, OFFICE	10. FIELD OR WILDCAT NAME E. Loving (Delaware)	
2412 N. Grandview, Suite 201, Odessa, Tx. 79761 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1387	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11, T23S, R28E	
AT SURFACE: 1378' FEL & 1977' FNL AT TOP PROD. INTERVAL: 2271' FEL & 1977' FNL AT TOTAL DEPTH: 2349' FEL & 1977' FNL	12. COUNTY OR PARISH 13. STATE Eddy NM	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. 30-015-26527	
REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3013.5 KB	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded @ 2:30 P.M. Drilled to 575'. Ran 8-5/8" 24# K-55 to 575'. 3/6/91 Cemented w/350 sx "C" w/2% S-1, .25%/sx D-29. Circ. 75 sx to pit.NU wellhead.

3/7/91 Tested casing to 1500#. Resumed drilling.

Attempted DST 5910-5979 packer failed. 3/19/91

3/21/91 Drilled to TD of 6500'. Ran CNL, CDL, CAL, DLL, MLL, & EPT.

Ran 5-1/2" 15.50# J-55 casing to TD. DV tool @ 3652'. Cemented 1st 3/22/91 stage w/300 sx 50/50 Poz. "C", 2% D-20, 11.5% D-42, 0.2% D-46, .5% D-65, 2% S-1, 0.5% EX 67749 & 150 sx "C", 2% D-46, .35% D-65, & .45% EX 67749. Open DV. Circ. 3 hrs. Cemented 2nd stage w/1000 sx 35/65 Poz. "C" 6% D-20, 10% D-44, & 100 sx "C" w/2% S-1. Circ. 180 sx to pit. Released rig.

	Sat @ Ft
Subsurface Safety Valve: Manu. and Type	 3et @

18. I hereby certify that the foregoing is true and correct

Sr. Prod. Engr. DATE _ 4/1/91

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

JS 199 CARLSBAD, NEW MEXIC

(NOTE: Report results of multiple completion or zone

change on Form 9-330.)