

11. Surface Restored

- A. This is private surface, and a damage agreement is being negotiated with Mississippi Chemical Corp., P. O. Box 101, Carlsbad, New Mexico, 88220, the surface owner.

12. Other Information

- A. The general location of this site is a sand dune and mesquite brush area. The sand has a very small amount of vegetation and stockpiling of material is not planned.
- B. The vegetation is dune-desert characterized by various species of cacti and mesquite.
- C. Wildlife species that occur in the area include: rabbits, muledeer, coyote, snakes and various rodents.
- D. An archaeological survey of the site and proposed access road has been conducted by the B.L.M.

13. Operator's Representative and Certification

- A. The field representatives responsible for assuring compliance with the approved surface use plan are:

	Office	Home
Operations Manager Fritz Schoch	915-362-6302	915-683-3635
Sr. Production Engineer Jim Shatzsall	915-362-6302	915-699-1210
Field Foreman - Construction David Mitchell	505-745-2329	505-397-6002
Compliance Gary Miller	915-682-4559	915-699-4672