

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

FEB - 6 1991

WELL API NO. 30-015-26542
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Amethyst State Com
8. Well No. 1
9. Pool name or Wildcat Undesignated Rustler Bluff

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMITS, OFFICE
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Nearburg Producing Company
3. Address of Operator P. O. Box 823085, Dallas, Texas 75382-3085	4. Well Location Unit Letter <u>E</u> : <u>1,880</u> Feet From The <u>north</u> Line and <u>990</u> Feet From The <u>west</u> Line Section <u>32</u> Township <u>24S</u> Range <u>29ENMPM</u> Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>2,903.3' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☒
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/23/90 Drilled 8-3/4" hole to 10,200'. Ran 10,200' (254 jts) of 7", 23#, 26#, 29#, S-95, L-80, P-110, N-80 (S-95 Buttress, N-80 Buttress) casing. Cemented w/300 sx 50/50 Poz w/2% gel and .5% Halad 322. Top of cement by temperature survey 8,400' KB.
12/24/90 Test casing and shoe to 1,000 psi for 30 minutes. WOC 18 hrs.
01/23/91 Drilled 6" hole to 13,478'.
01/24/91 Logging.
01/25/91 Logging.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Machelle Byrum TITLE Production Secretary DATE 2/4/91

TYPE OR PRINT NAME Machelle Byrum

TELEPHONE NO. 214/739-1778

(This space for State Use) ORIGINAL SIGNED BY

MIKE WILLIAMS

APPROVED BY SUPERVISOR, DISTRICT II

TITLE

DATE FEB 7 1991

CONDITIONS OF APPROVAL, IF ANY: