

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.

30-015-26749

5. Indicate Type of Lease

STATE ☐ FEE ☐

6. State Oil & Gas Lease No.

115000

7. Lease Name or Unit Agreement Name:

Pardue Farms

8. Well No.

#4

9. Pool name or Wildcat

Loving East Delaware

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Kerr-McGee Oil & Gas Onshore LLC

3. Address of Operator

P. O. Box 809004, Dallas, TX 75380-9004

4. Well Location

Unit Letter A-10-23S-2 : 660 feet from the North line and 660 feet from the East line

Section 10 Township 23S Range 28E NMPM County Eddy

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

2998'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Temporarily Abandonment ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

This Approval of Temporary Abandonment Expires 3/2006

This well has been temporarily abandoned as per the following procedures:

1-22-1994 Perfs 6108-6146 were squeezed and a cement retainer was set at 6051'

2-06-2001 Baker Mod. 'R' Pkr set at 5774' thereby isolating perfs from 5814-6146.
(Note: these perfs were never productive.)
Casing was pressure tested to 580# for 30 minutes with no loss of pressure. Chart is attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Beverly Lakin TITLE Proration Analyst DATE 03-05-01

Type or print name Beverly Lakin Telephone No. 972 715-4830

(This space for State use)

APPROVED BY Beverly Lakin TITLE Field Rep DATE 3/26/01
Conditions of approval, if any:

