

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

JUL 25 1992

O. C. D.

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Pardue Farms 26

8. Well No.

4

9. Pool name or Wildcat

East Loving Delaware

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

Parker & Parsley Development Company

3. Address of Operator

P.O. Box 3178, Midland, Texas 79702

4. Well Location

Unit Letter C : 2100 Feet From The West Line and 560 Feet From The North Line

Section 26

Township 23S

Range 28E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3016' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: Pump test Bone Springs ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Remove CIBP @ 6290' ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-21-92 RU DA&S Well Service. POOH w/ rods, pmp & tbg. SDFN.

Will drill out CIBP, which does not have the Bone Springs properly plugged back. As discussed w/ Mike Williams, request permission to pump test Bone Springs w/ Brushy Canyon to recover frac load and gather production data necessary to file for permit to commingle the Brushy Canyon and Bone Springs. If fluid volumes will not allow commingling (after 3 day pump test) the Bone Springs will be plugged back correctly. The workover rig will be moved to the Pardue Farms 27 #10 from the Pardue Farms 26 #4 to perform same operation.

29

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*J. Michael Reeves*

TITLE

District Manager

DATE

7/22/92

915

TYPE OR PRINT NAME

J. Michael Reeves

TELEPHONE NO. 683-4768

(This space for State Use)

ORIGINAL SIGNED BY

MIKE WILLIAMS

SUPERVISOR, DISTRICT II

APPROVED BY

TITLE

DATE

AUG 17 1992

CONDITIONS OF APPROVAL, IF ANY: