BUREA	UNITED STATES RTMENT OF THE INTERIOR U OF LAND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM, 51073	
Do not use this form for proposal	FICES AND REPORTS ON WELLS s to drill or to deepen or reentry to a different reservoir DN FOR PERMIT—'' for such proposals RECEIVED		
SU	7. If Unit or CA, Agreement Designation		
 Type of Well Oil Well Other Name of Operator Collins & Ware, Inc. Address and Telephone No. 303 W. Wall, Suite 2200, M Location of Well (Footage, Sec., T., R., M., or 1433' FSL & 1459' FEL of S CHECK APPROPRIATE 	Survey Description)	8. Well Name and No. Muley Federal 9. API Well No. 10. Field and Pool, or Exploratory Area Horseshoe Bend (Strawn- 11. County or Parish, State Morrow) Eddy, New Mexico DRT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
Subsequent Report	Abandonment Recompletion Plugging Back Casing Repair Altering Casing	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water	
	XX Other <u>7'' Casing Report</u>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

An eight and one-half inch hole was drilled to a depth of 9000' K.B. on June 21, 1992. Two hundred and twenty seven joints of 32 and 29#/ft., N-80, S-95 and P-110 LT&C casing was run and set at 9000' K.B. Ran 2 D.V. tools; one at 5110.36' K.B. and one at 1962.65' K.B. Cemented first stage with 450 sacks Halliburton Lite Premium Cement with 5# salt/sk., 1/4# flocele/sk., 5# gilsonite/sk. (1.93 cu.ft./sk. yield, 12.7#/gallon). Tailed in with 150 sacks Premium cement with 2.5# KCL/sk., 0.6% Halad 14, 5# silicalite/sk., (1.34 cu.ft./sk. yield, 15.1#/gallon). Displaced hole and plug down at 11:15 PM June 21, 1992. Opened D.V. tool, did not have returns. Circulated for 4.25 hours pumping 10 barrels every 15 minutes. Closed first D.V. tool, did not cement. Cemented third stage with 50 sacks Halliburton Lite Premium Plus cement with 5# salt/sk., 1/4# flocele/sk., 5# gilsonite/sk., 5# gilsonite/sk., (1.84 cu.ft./sk. yield, 12.7#/gallon). 150 sacks Halliburton Lite Premium Plus Neat cement (1.84 cu.ft./sk. yield, 12.7#/gallon). Tailed in with 50 sacks Premium Plus cement with 2% CACL2 (1.32 cu.ft./sk. yield, 14.8#/gallon). Plug down at 8:00 AM June 22, 1992. Circulated 30 sacks cement to pit. Waited on cement 24 hours. Tested BOP to 10,000 psig, hydrill to 2500 psig. Closed first D.V. tool and tested casing to 2000 psig,0.K.

A state of the and thread	1		
14. I hereby certify that the foregoing is true and correct Signed Ballie + Contact	Title Agent	for Collins & Ware, Inc.	Date July 10, 1992
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	A	NPare VIII

Title 18 U.S.C. Section 1001, makes it a ctime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements