

12015 1992

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-215-27420
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-3589
7. Lease Name or Unit Agreement Name Pauline ALB State
8. Well No. 5
9. Pool name or Wildcat Wildcat Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210
4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line Section 32 Township 23S Range 31E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3386' GR
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Production Casing, Perforate, Treat <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
TD 8150'. Reached TD 11-29-92. Ram 196 joints 5-1/2" 15.5# and 17# J-55 casing set 8150'. Float shoe set 8150', float collar set 8107'. DV tool set 6718'. Cmt'd in 2 stages. Stage 1: 200 sx "H" w/8#/sx CSE, 5#/sx Gilsonite, .6% CF-14, .35% Thriflylite (yield 1.75, wt 13.6). Tailed in w/65 sx "H" w/10% Thixad, 8#/sx Hiseal, 10% Salt (yield 1.38, 25 15.5). PD 2:47 AM 12-1-92. Circulated 77 sacks Circulated thru DV tool 4 hours. Stage 2: 600 sx PSL "C" w/5#/sx Gilsonite, .4% CF-14, 5#/sx Salt (yield 1.85, wt 12.6). Tailed in w/150 sx "H" w/8#/sx CSE, 5#/sx Gilsonite, .6% CF-14, .35% Thriftylite (yield 1.75, wt 13.6). PD 7:53 AM 12-1-92. Bumped plug to 2500 psi, held OK. WOC 24 hours. Drilled DV tool at 6718'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <i>Juanita Goodlett</i>	TITLE Production Supervisor	DATE 12-14-92
TYPE OR PRINT NAME Juanita Goodlett	TELEPHONE NO. 505/748-1471	

(This space for State Use) ORIGINAL SIGNED BY
MIKE WILLIAMS,
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE DEC 20 1992

CONDITIONS OF APPROVAL, IF ANY: