

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

+
c15f
bp

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED
JAN 05 1993
O. C. D.

WELL API NO. 30-015-27155
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-3589
7. Lease Name or Unit Agreement Name Pauline ALB State
8. Well No. 7
9. Pool name or Wildcat Wildcat Delaware
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3383' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210
4. Well Location Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line Section 32 Township 23S Range 31E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3383' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Production Casing <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8080'. Reached TD 11-30 PM 12-28-92. Ran 181 joints 15.5# and 17# J-55 casing set 8080'. Float shoe set 8080', float collar set 8035'. DV tool set 6708'. Cemented in two stages as follows: Stage I - 250 sx "H" + 8#/sx CSE + 5#/sx Gilsonite + .6% CF-14 + .35% Thriftylite (yield 1.75, wt 13.6). PD 5:49 AM 12-30-92. Did not bump plug. Circulated 51 sacks. Circulated through DV tool 4 hours. Stage II - 550 sx PSL "C" + 5#/sx Salt + 5#/sx Gilsonite + .4% CF-14 (yield 1.85, wt 12.7). Tailed in w/150 sx "H" + 8#/sx CSE + 5#/sx Gilsonite + .6% CF-14 + .35% Thriftylite (yield 1.75, wt 13.6). PD 10:59 AM 12-30-92. Bumped plug to 2750 psi for 1 minute; float and casing held OK. WOC 18 hours.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 1-4-93

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE JAN 12 1993

CONDITIONS OF APPROVAL, IF ANY: