

RECEIVED

OCT 18 1993

WELL-SITE EVALUATION FIELD FORM

Company Name

Devon

Well Name

C.L.D.
Todd 25E Fed. #6

Location: Section

25

T. 23

S., R. 31

E., Footage

1650' FN2+WL

Examined by

B. Host

Date

5/17/93

Description and Topography: (cuts, fills, etc.)

Flat

Soils: (reseeding strips, etc.)

Sandy #2

Hydrogeology: (wells, springs, streams, plant indicators, windmills, etc.)

None close

Wildlife: (habitat, etc.)

None seen. Shinnery oak/Yucca/sand sage/mesq.

Caliche Location:

?

Cave Area:

N/A

Other: (VRM, plant habitat, WSA, archaeology, livestock conflicts, etc.)

Existing gas well about 300 ft. southeast.

Evaluation:

OK