

WELL-SITE EVALUATION FIELD FORM

Company Name Devon Well Name Todd 25 K Rd. #11

Location: Section 25, T. 23 S., R. 31 E., Footage 1280' BS+WL

Examined by B. Vot Date 5/17/93

Description and Topography: (cuts, fills, etc.) Flat

Soils: (reseeding strips, etc.) Sandy

Hydrogeology: (wells, springs, streams, plant indicators, windmills, etc.)

None Obs

Wildlife: (habitat, etc.) None seen. Shinnery oak / Yucca / Sand Sage / Mesq.
Type

Caliche Location: ?

Cave Area: N/A

Other: (VRM, plant habitat, WSA, archaeology, livestock conflicts, etc.)

Evaluation: OK