

YATES PETROLEUM CORPORATION
Llama ALL Federal #1
Section 7-T22S-R31E
Eddy County, New Mexico

RESULTS OF DRILL STEM TESTS

DST #1 5337-5387' (Brushy Canyon): TIMES: TO 30"; SI 60"; TO 60"; SI 120"; TO 60".
RECOVERY: 279' of oil & 934' of water. SAMPLER: .41 cfg, 300 cc oil and 2000 cc
water. PRESSURES: IHP 2336; IFP 103-180; ISIP 2231; 2nd FP 309-412; 2nd SIP 2283;
FFP 515-541; FSIP 2336.

DST #2 12810-12856' (Atoka): TIMES: TO 30"; SI 60"; TO 90"; SI 180". RECOVERY:
1475' of water cushion with trace of mud and condensate. SAMPLER: 9.2 cfg with small
trace of condensate. PRESSURES: IHP 6827; IFP 1505-1570; ISIP 2379; 2nd FP
1025-1570; 2nd SIP 2379; FHP 6827.