

YATES PETROLEUM CORPORATION
Pescador AQV State Com #1
Section 6-T24S-R24E
Eddy County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 2528-2598' (Delaware): TIMES: TO 20"; SI 60"; TO 60"; SI 120"; TO 60".
RECOVERY: 360' of rathole mud and 1100' of formation water. SAMPLER: 2500
cc water. PRESSURES: IHP 1255; IFP 110-407; ISIP 892; 2nd FP 414-626; 2nd SIP
895; FFP 628-749; FHP 1258

DST #2 9462-9526' (Atoka): TIMES: TO 20"; SI 60"; TO 60"; SI 120"; TO 60".
RECOVERY: 150' of rathole mud. SAMPLER: 2500 cc mud. PRESSURES: IHP 4806;
IFP 153-209; ISIP 315; 2nd FP 243-270; 2nd SIP 553; FFP 150-112; FHP 4805

DST #3 10254-10312' (Morrow): TIMES: TO 20'; SI 60"; TO 60"; SI 120"; TO 60".
RECOVERY: 85' of mud. SAMPLER: .08 cfg, 1800 cc mud. PRESSURES: IHP 5208;
IFP 68-73; ISIP 252; 2nd FP 55-71; 2nd SIP 568; FFP 49-72; FHP 5211