

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
gy. Minerals and Natural Resources Departm

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-30295

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
OXY USA Inc. 16696

3. Address of Operator
P.O. Box 50250 Midland, TX 79710-0250

4. Well Location
Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line
Section 32 Township 23S Range 26E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3429'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐ CASING TEST AND CEMENT JOB ☒

OTHER: ☐ OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See other side

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Regulatory Analyst DATE 8/6/98
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915685571

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE 8-10-98

CONDITIONS OF APPROVAL, IF ANY

ATTACHMENT C-103
OXY USA INC.
OXY ZEPHYR STATE #1
SEC 32 T23S R26E
EDDY COUNTY, NM

NOTIFIED NMOCD 7/4/98, MIRU MCWAY #10, SPUD WELL 0800hrs MDT 7/5/98. DRILL 17-1/2" HOLE TO TD @ 432' 7/5/98, CHC. RIH W/ 13-3/8" 48# CSG & SET @ 432'. M&P 200sx 65/35/6 C/POZ/GEL W/ 2% CaCl₂ + .25#/sx CELLOFLAKE FOLLOWED BY 200sx Cl C CMT W/ 2% CaCl₂, DISP W/ FW, PLUG DOWN @ 0200hrs MDT 7/6/98, CIRCULATE 53sx CMT TO PIT, WOC-18hrs. NMOCD NOTIFIED, BUT DID NOT WITNESS. CUT OFF CSG & WELD ON WELLHEAD, TEST, OK. NU 5000# BOP & 3000# HYDRIL & TEST TO 500#, OK. RIH & DO CMT, TEST CSG, OK, DRILL AHEAD.

DRILL 12-1/4" HOLE TO TD @ 2300' 7/8/98, M&P HIGH VIS SWEEP. RIH W/ 8-5/8" 24# CSG & SET @ 2300'. M&P 800sx 65/35/6 C/POZ/GEL + 5#/sx SALT + 5#/sx GILSONITE + .25#/sx CELLOFLAKE, FOLLOWED BY 200sx Cl C CMT W/ 2% CaCl₂, DISP W/ FW, PLUG DOWN @ 0800hrs MDT 7/9/98, CIRC 184sx CMT TO PIT, WOC-18hrs. NMOCD NOTIFIED, BUT DID NOT WITNESS. NDBOP, SET SLIPS, CUT CSG, NUWH, TEST TO 1500#, OK. NU BOP'S & TEST TO 5000#, OK. RIH & TAG CMT, DO CMT, TEST CASING, HELD OK, DRILL AHEAD.