

WELL TEST INTERPRETATION REPORT #:1070344		PAGE: 2,
CLIENT : EGL RESOURCES, INC.		1-SEP-99
REGION :CSD	SEQUENCE OF EVENTS	FIELD:BLDRDG CANY #2
DISTRICT:HOBBS		ZONE :UPPER MORROW
BASE :MIDLAND		WELL :BALDY CAN #2
ENGINEER:BILL GRAYSHAW		LOCATION:13/24s/24e

DATE	TIME (HR:MIN)	DESCRIPTION	ET (MINS)	BHP (PSIA)	WHP (PSIG)
=====					
31-AUG		OPEN TO 1/8" BUBBLE HOSE			
	03:13	HYDROSTATIC MUD	-4	5274	
	03:15	SET PACKERS	-2		
	03:17	START FLOW	0	134	1"
		B.O.B. @ 32 SECONDS			
	03:18		1		2.2#
	03:20		3		2.8#
	03:22		5		3.2#
	03:27		10		4.1#
	03:33	END FLOW & START SHUT-IN	16	86	4.4#
	03:38	OPEN TO 1" CHOKE ONLY	21		
	04:16	OPEN TO BUBBLE HOSE ONLY	59		
	04:17	END SHUT-IN	60	2229	
	04:21	START FLOW	64	150	1/2"
		B.O.B. @ 48 SECONDS			
	04:22		65		12oz.
	04:23		66		1.9#
	04:26		69		2.0#
	04:31		74		2.2#
	04:36		79		2.4#
	04:51		94		2.9#
	05:06	END FLOW & START SHUT-IN	109	189	3.1#
	05:09	OPEN TO 1" CHOKE ONLY	112		
	07:15	END SHUT-IN	238	3607	
	07:18	PULLED PACKERS LOOSE	241		
	07:19	HYDROSTATIC MUD	242	5283	
		PULLED TO FLUID			