

WELL TEST INTERPRET: EPORT #:6198192		PAGE: 3, 14-JUN-00
CLIENT : KUKUI OPERATING COMPANY		
REGION :CSD DISTRICT:HOBBS BASE :MIDLAND ENGINEER:ROY CHERRY JR.	SEQUENCE OF EVENTS Continued	FIELD: CEDAR CANYON ZONE :WOLFCAMP WELL :GOODNIGHT 35 F LOCATION:S35T23sR29e

DATE	TIME (HR:MIN)	DESCRIPTION	ET (MINS)	BHP (PSIA)	WHP (PSIG)
=====					
	18:16	" 13.61 MMCF/D	135		5600*
	18:21	" 13.37 MMCF/D	140		5500*
	18:26	END FLOW & START SHUT-IN BLOW DOWN GAS TO FLARE	145	8397	5700*
	20:37	END SHUT-IN	276	8771	0
	20:47	DROP BAR AND BEGIN U-TUBE	286		1500
11-JUN		Circulated mud, became stuck. BEGAN JARRING			
	18:48	CYCLED TOOL OPEN & SHUT	1607		
13-JUN	17:00	COMPLETED FISHING JOB	4379		