Submit 3 Copies To Appropriate Disma 14151' State of New Mex Office	
District I 1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II Bill South First, Artesia, NM 87210 District III District IIII District III District II District	5 Indicate Type of Lease
District III RECEIVED N2040 South Pache 1000 Rio Brazos Rd., Aztec, MM 874100 - ARTESIA Santa Fe, NM 87.	SOS STATE FEE
District IV Stanta Fe, NM 87505 2040 South Pacheco, Santa Fe, NM 87505	6. State Oil & Gas Lease No. VO - 6377
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOI	G BACK TO A R SUCH 7. Lease Name or Unit Agreement Name:
PROPOSALS.) 1. Type of Well:	El Presidente State
Oil Well Gas Well Other 2. Name of Operator	8. Well No.
Nadel and Gussman Permian, L.L.C. COGRID # 1	
3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701	9. Pool name or Wildcat Black River Atoka/ Morrow
4. Well Location	
Unit Letter <u>H</u> : <u>1930</u> , feet from the <u>North</u> line and <u>760</u> , feet from the <u>East</u> line	
Section 2 Township 24 - S Range	e 27 - E NMPM Eddy County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3149' GL, 3166' KB 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	REMEDIAL WORK
TEMPORARILY ABANDON CHANGE PLANS	
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST AND
	OTHER re-cement casing tops
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.	
03/05/02 A leak developed between the 13-3/8" casing and 20" conductor pipe. Van Barton with the Artesia NMOCD authorized the repair procedures. MIRU BJ services and pumped 200 sx neat with 2% to 4% CaCl tail into the A section. WOC 2 hours and pumped 75 sx C neat with 6% CaCl. Had no flow to pit or outside 13-3/8" casing. WOC 1½ hours and hooked BJ up to the B section (9-5/8" x 5½" annulus). Pumped 125 sx C with 2% to 6% CaCl. After 75 sx were pumped, flow was observed outside of the 13-3/8" casing. Cement filled the cellar and covered the outside of the A section. Shut in the B section and moved out BJ. After 2 hours, gas was bubbling in the cellar between the 20" conductor and 13-3/8" casing. Had a slight gas blow after 4 hours.	
03/0702 MI Howco logging. RU logging packoff and MI Key pump truck. Tested packoff to 1500 psi - OK. RIH with logging tools. Logged from 12,630' to 100' with CAST-V bond log with standard VDL CBL and temp survey in selected intervals. RD and released Howco and Key pump truck. Gas flow rate from B section valve through 2" pipe to fenced-off reserve pit is less than 5 mcfpd.	
Will run line from wellhead to the tanks to bleed pressure off the casing.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURETITLE	Operations Engineer DATE 3-13-02
Type or print name Robert McNaughton	Telephone No. 915 - 682 - 4429
(This space for State us) ORIGINAL SIGNED BY THE W.	DATEAR 1 5 202
APPPROVED BY	DATE
Conditions of approval, if any:	