

11. Surface Ownership

1. The wellsite is on BLM surface.

12. Other information

1. Topography: See 7.5' Series Kitchen Cove, NM (Prov. Ed. 1985) 32104-C3. Exhibit "B". GL elevation is 3328'.
2. Soil: NRCS: Regan-Upton association: Loamy, deep soils and soils that are shallow to caliche; from old alluvium.
3. Flora and Fauna: Vegetation cover is approximately 15% overall and consists primarily of tar bush, acacia, walking stick, cholla cactus, prickly pear cactus, eagle talon cactus, creosotebush, broom snakeweed, crucifixion thorn, littleleaf horsebrush, various grasses and other flora.
4. Ponds and streams: There are no rivers, streams, lakes or ponds in the area.
5. Residences and Other Structures: None location.
6. Archaeological, Historical and Cultural Sites: Geo-Marine Inc. has completed an Class III Archaeological Survey, see attached exhibit "A".
7. Land Use: Grazing.
8. The well site, if a producer, will be maintained and kept clean of all trash and litter, which detracts from the surrounding environment. Equipment will be maintained in accordance with good operating practice.
9. After the well site is cleaned and pits and sumps backfilled, any obstruction to the natural drainage will be corrected by ditching or terracing. All disturbed areas, including any access road no longer needed, will be ripped. Those areas will be reseeded with grass in accordance with BLM stipulations.