600 East Las Colinas Blvd. Suite 1100 Irving, TX 75039 972-401-3111 (phone) 469-420-2710 (fax)

Gruy Petroleum Management Co

January 6, 2003

Bureau of Land Management 2909 West Second Street Roswell, New Mexico 88201-2019 Attn: Alexis Swaboda

RE: Pennzoil Federal Com 3 30-015-32540 Section 15; T 24S; R 26E Eddy County, NM

Dear Alexis Swaboda:

Please find enclosed (1) one original and (5) five copies of Form 3160-5, Sundry Notice, for the above referenced well notifying you of the setting of surface and intermediate casing.

If you should have any questions or need further information, please feel free to contact Zeno Farris at 972-443-6489.

Sincerely,

Natalie Alsengen

Natalie Krueger Production Assistant

Enclosure

CC: Wadi Petroleum, Inc. 14405 Walters Rd., Suite 400 Houston, TX 77014 Attn: Mr. Kevin B. Dice

nkrueger@magnumhunter.com

New Mexico Oil Conservation Division 1301 West Grand Avenue Artesia, NM 88210 Attn: Mr. Bryan Arrant



					,	150	1001017				
Form 3160-5 (November 1994)	UNITED STATES DEPARTMENT OF THE L BUREAU OF LAND MANA				ERIOR	34501001017		FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996 5. Lease Serial No. NM 04022170			
	SUNDR	TO A CONTRACT OF LAND MANAGEMENT									
Do not use this form for proposals to drill or to re-e abandoned well. Use Form 3160-3 (APD) for such pro					ll or to re-ente	er an and		6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other Instructions on reverse side							Beccult	7. If Unit or CA/Agreement, Name and/or No. SRM 1'15			
1. Type of Well Oil Well Gas Well Other								8. Well N	Name: and No.		
2. Name of Operator Gruy Petroleum Management Co.								Pennzoil Federal Com No. 3 9. API Well No.			
3a. Address 3b 3c					b. Phone No. (include area code) 972-401-3111			30-015-32540 10. Field and Pool, or Exploratory Area			
	-		M., or Survey Descriptio	n)					e City; Perin (Gas)		
2000' FSL & 660' FEL Sec. 15 T24S - R26E									y or Parish, State CO., NM		
	12. CHECK AP	PROP	RIATE BOX(ES) T	O IN	NDICATE NAT	URE C	OF NOTICE, R	EPORT, C	DR OTHER DATA		
TYPE OF SUBMISSION				TYPE OF ACTION							
Notice of	Intent		Acidize		Deepen		Production (Star	rt/Resume)	Water Shut-Off		
			Alter Casing		Fracture Treat		Reclamation		Well Integrity		
Subsequer	at Report		Casing Repair		New Construction	_	Recomplete Temporarily Ab	bandon Other Set Surface &			
Ginal Abandonment Notice			Change Plans Convert to Injection		Plug and Abandor Plug Back		Water Disposal				
If the propose Attach the E following co testing has b	al is to deepen dire tond under which the impletion of the invo- een completed. Fi hat the site is ready	ctionally ne work olved op nal Aba for final	y or recomplete horizonta will be performed or pro- perations. If the operation ndonment Notices shall inspection.)	ally, g ovide on res be fil	tive subsurface loca the Bond No. on f ults in a multiple co ed only after all re	itions and ile with completion quiremen	d measured and tra BLM/BIA. Requi n or recompletion nts, including recla	ue vertical de ired subseque in a new inte amation, have	work: and approximate duration there pths of all pertinent markers and zon ent reports shall be filed within 30 d erval, a Form 3160-4 shall be filed o e been completed, and the operator		
12/16/02	•						-		0 8rd ST&C new casing.		
								•	ailed with 150 sx Premium		
	Plus Cement	+2% (CaCl - plugged dov	vn 8	bumped with	350#.	Circulated 12	20 sx cem	ent to surface. WOC		
	19 hrs.										
12/21/02							-		d ST&C new casing. Lead		
			"C"+1/4# Flocele own & Bumped wit						nt+1%CaCl+1/4# Flocele WOC 19 hrs.		
14. I hereby cer Name (Prin	tify that the foregoin ted/Typed)	ng is true	e and correct		Title						
					Pro	ductio	n Assistant				
Signature Nataliakuvar					Date Ja	Date January 3, 2003					
		Ô	THIS SPACE	FOR	FEDERAL OR	STATE	E OFFICE USE				
Approved by					Title			Date			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					Office						
Title 18 U.S.C.	Section 1001, make	s it a cr	time for any person know o any matter within its im	wingly risdic	y and willfully to n tion.	nake to a	any department or	agency of th	ne United States any false, fictitious		
(Instructions on							,				

	Magnum Hunter Production, Inc.
	Well History $OCD = ADres$
	Well History $OCD - APTESIA$ December 16, 2002 Thru December 23, 20023
OPERATED	Well History December 16, 2002 Thru December 23, 2002
NM OTHER NON	OP
	UM MANAGEMENT CO IL FEDERAL COM 3 W.I. Pct BCP 12.76 % W.I. Pct BCP 12.76 %
EDDY, NM	IL FEDERAL COM 3 W.I. Pct ACP 12.76 % 15-T24S-R26E Morrow / 12,000'
12/16/2002	Depth 61
AFE: 2215	Progress 0 Present Operation: Mixing spud mud
	Location staked by John West Surveying on 5/7/2002 - 2,000' FSL & 660' FEL of Sec. 15 T-24-S R-26-E in Eddy County, New Mexico. B&H Construction built location, pits & road from 11/25/2002 to 11/27/2002. Abbott Brothers set 20" conductor pipe at 38' FGL & cemented with ready mix - dug rat & mouse holes + 3 sump holes on 12/10/2002 & 12/11/2002. Akome, Inc. plastic lined & fenced reserve pit on 12/10/2002 - Great Basin put water in reserve pit to hold down the plastic on 12/10/02. MIRU Patterson-UTI Rig # 75 on 12/15/2002. Welded flow nipple onto conductor pipe - mixed spud mud - preparing to spud well.
12/17/2002	Depth 460
AFE: 22151	Progress 399 Present Operation: NU BOPs & Choke Manifold
	Drilling from 61' to 241' (Spud a 17 1/2" hole at 6:00 AM (CST) 12/16/2002) Service rig WLS @ 194' = 10 Drilling from 241' to 460' TD (Reached TD of 17 1/2" hole at 4:30 PM (CST) 12/16/2002) Circulate & pump sweep Drop Totco @ 460' = $3/40$ & trip out - LD roller reamer, shock sub, bit sub & bit RU csg. crew & ran 11 jts. 13 3/8" 48# H-40 8rd ST&C new casing (464.30') - set at 460' KB - KB to GL = $23.00'$ - ran 5 Halliburton centralizers: 445', 339', 220', 130' & 41' KB. Circulate to clear casing Hall. cemented 13 3/8" csg. (Lead) 340 sx Prem. Plus Cement + 4% Gel + 2% CaCl + $1/4#$ Flocele per sx, (Tail) 150 sx Prem. Plus Cement + 2% CaCl - plug down & bumped with 350# at 9:20 PM (CST) 12/16/02 - circulated 120 sx cement to surface - Paul Swartz w/ the BLM witnessed job. WOC & cut off 20" conductor pipe Cut off 13 3/8" csg. & weld on a 13 3/8" SO X 13 5/8" 3,000# braden head & test to 500# - OK NU BOP's & choke manifold
12/18/2002	Depth 1,090 Progress 630
AFE: 22151	Present Operation: Drlg
	NU BOP & choke manifold Test Bop blind rams, choke manifold, 13 3/8" casing & well head to 775# - OK Service rig TIH with Bit # 2, Sperry Sun 8" mud motor, reamer, 8" DC, stab.& 8" DC's - tagged up @ 401' Drill cement, wiper plug, float collar & cement from 401' to 430' Test Bop pipe rams, hydril, choke manifold, 13 3/8" casing & well head to 500# - OK - BLM was notified of tests, but did not witness the tests Drill remainder of cement & shoe from 430' to 460' Drill from 460' to 964' (88 RPM motor & 50 RPM rotary, back on formation at 5:45 PM CST 12/17/02) WLS @ 890' = 3/40 Drill from 964' to 1,090' (88 RPM motor & 50 RPM rotary)
12/19/2002	Depth 1,722
AFE: 22151	Progress 632 Present Operation: Drlg
January 3, 2003	Drill from 1,090' to 1,375' (88 RPM motor & 50 RPM rotary - 10K to 35K bit wt.) WLS @ $1,300' = 2 1/40$ Drill from 1,375' to 1,407' (88 RPM motor & 50 RPM rotary - 10K to 15K bit wt.) Service rig & install rotating drilling flow nipple Drill from 1,407' to 1,565' (88 RPM motor & 50 RPM rotary - 15K to 25 K bit wt.) WLS @ 1,491' = 1 1/40 Drill from 1,565' to 1,722' (88 RPM motor & 50 RPM rotary - 20K to 30K PENNZOIL FEDERAL COM 3

Gruy Petroleum Management Co. Magnum Hunter Production, Inc.

-74

Já

	on wij
1:2/20/2002	Depth 2,490
AFE: 22151	Progress 768 Present Operation: Drilling
	Drill from 1,722' to 1,786' (88 RPM motor & 50 RPM rotary - 25K to 30K bit wt.) Service rig WLS @ 1,712' = 3/40 Drill from 1,786' to 2,071' (88 RPM motor & 50 RPM rotary - 40K to 45K bit wt.) WLS @ 1,997' = 1/20 Drill from 2,071' to 2,490' (88 RPM motor & 50 RPM rotary - 50K bit wt.)
12/21/2002 Maintenance	
AFE: 22151	Present Operation: POOH
	Drill from 2,490' to 2,576' (88 RPM motor & 50 RPM rotary - 50K bit wt.) Service rig WLS @ 2,497' = 1 1/40 Drill from 2,576' to 2,925' (88 RPM motor & 50 RPM rotary - 50K to 55K bit wt.) WLS @ 2,851' = 3/40 Drill from 2,925' to 3,220' TD (88 RPM motor & 50 RPM rotary - 55K bit wt.) reached TD of 12 1/4" hole at 3:30 AM CST 12/21/2002 - Ran Davis Fluid Caliper from 3,115' to 3,135', it will take 1,802 ft.3 (without excess) cement with 9 5/8" casing to circulate cement at 3,220' TD Pump 60 bbl. viscous sweep & circulate Drop Totco & POOH standing back 4 1/2" DP - found cracked jt. of DP - bottom jt. of the 25th stand out - 36 1/2" down from box end - horizontal crack - LD bad jt. of DP
12/22/2002	
Maintenance AFE: 22151	Present Operation: TIH
	RU laydown machine & POOH LD 8" DC's, IBS, reamer & Bit # 2 12 1/4" Security XL43N Serial #10394366 3-14's in @ 460' out @ 3,220' cut 2,760' in 79 1/4 hrs. condition = T2 B4 In gauge RU casing crew & ran 72 jts. 9 5/8" 40# J-55 8rd ST&C new casing (See Casing Detail) - 3,224.42' - set at 3,220' KB RU Halliburton & circulate to clear casing Halliburton cemented 9 5/8" casing (Lead) 900 sx Interfill "C" + 1/4# Flocele per sx, followed by (Tail) 200 sx Premium Plus Cement + 1% CaCl + 1/4# Flocele per sx - plug down & bumped with 1,400# at 3:35 PM 12/21/02 - circulated 205 sx cement to surface - BLM was notified - didn't witness job ND & PU BOP - set 9 5/8" casing slips in 100,000# - cut off 9 5/8" casing - installed a 13 5/8" 3M X 11" 5M "B" Section Spool & tested same to 1,500# - OK - NU BOP's & choke manifold Test BOP, choke manifold & associated equipment to 5,000# - OK - NU BOP's & choke manifold Test BOP, choke manifold & associated equipment to 5,000# - OK - Paul Swartz with the BLM witnessed the test - accumulator test failed - will have to make repairs before drilling out cement Install wear bushing PU & TIH with Bit # 3 & BHA
12/23/2002 Maintenance AFE: 22151	Present Operation - Drilling
ALC. 22131	Present Operation: Drilling
	PU & TIH with Bit # 3, mud motor, reamer, 6 3/4" DC, IBS, 6 3/4" DC, IBS, 4 - 6 3/4" DC's, X~O sub & 25 - 6 1/8" DC's - test motor - OK TIH with 4 1/2" DP out of derrick - (LD 10 jts. DP) - tagged up on cement (a) 3,157" - made repairs on BOP accumulator (replaced one bad bladder & repaired 4 way valve to hydril) Test 9 5/8" casing, well head & BOP to 2,200# - OK (had to change out 1 bad 2" valve & a gasket in a 2" union that was leaking) Drill cement, plug, float collar, cement & shoe from 3,157' to 3,220' Drill from 3,220' to 3,239' (back on formation at 10:30 AM CST 12/22/2002) Service rig Test formation at 3,239' to a 10.8#/gal. mud wt. equivalent with 8.4#/gal. fluid in the hole with 400# - OK - welder RU EPOCH flow line sensor adapter, RPM read out & stand for EPOCH monitor Drill from 3,239' to 3,787' (159 RPM motor & 34 RPM rotary - 35K to 40K bit wt.) WLS (a) 3,717' = 10 Drill from 3,787' to 3,913' (158 RPM motor & 36 RPM rotary - 40K bit wt.)
	53450 2

Confector 3 2 1.94²⁰