			N.M. Ö		is. DIV-	nișt. 2	2		$C/S_{r}$	
Form 3160-5 (November 1994)		UNI STATES DEPARTMENT OF THE IN	1301	W. G	rand Av	ic.iue	F	ORM APPROVED MB No. 1004-0135	1/2	
(107010011777)	,	DEPARTMENT OF THE IN BUREAU OF LAND MANAG	TBRIOR ' TEMENT • & 2		NM 882	210	E	kpires July 31, 1996		
BUREAU OF LAND MANAGEMENT MOSIA, NM 8821 SUNDRY NOTICES AND REPORTS ON WELLS							<ul> <li>5. Lease Serial No.</li> <li>NM 0402170</li> </ul>			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.							6. If Indian, Allottee or Tribe Name			
£	SUBMIT IN TR	RIPLICATE - Other Instru	ctions on r	everse a	side	7.	If Unit or CA SW - 103	4/Agreement, Name a	nd/or No.	
1. Type of We		 ``]		22324	2526222					
Oil Well Gas Well Other				• • • • • • • • • • • • • • • • • • •			. Well Name and No. Federal 22 Com No. 2			
2. Name of Operator Gruy Petroleum Management Co.				9. API Well No. 30-015- 32486						
3a. Address         3b. I           P. O. Box 140907         Irving, TX 75014-0907				o. (inclyde 401-311	area code) EIVED			DJ 484 ol, or Exploratory Are		
				000	ARTESIA			; Penn (Gas)	24	
	4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 990' FNL & 660' FEL Sec. 22 T24S - R26E UT. A					•/	County or Pa Eddy Co.			
	12 CHECK AL	PPROPRIATE BOX(ES) TO		NATUR	E OF NOTIC	CE. REPO	RT. OR O	THER DATA		
					E OF ACTIO				<u> </u>	
	UBMISSION									
Notice of 1	Intent	Acidize	Deepen Fracture Ti	reat	Reclamati	n (Start/Resu	me) 🛄	Water Shut-Off Well Integrity		
Subsequer	nt Report	- Anter Cushig	New Const				2		Irface &	
<b>—</b>		Change Plans	Plug and A			ily Abandon		Intermediate C		
Final Aba	ndonment Notice	Convert to Injection	Plug Back		Water Dis	sposal				
following co testing has b	ompletion of the invocen completed. F that the site is ready Spud 17 1/2' Ran 5 Hallib	work will be performed or prov volved operations. If the operation inal Abandonment Notices shall be for final inspection.) " hole at 6:00 AM (CST). If urton centralizers. Lead w ed with 150 sx Premium PI	results in a mu filed only afte Reached TE ith 340 sx F	itiple complete r all require of 445'. Premium	letion or recomp ements, includin Ran 10 jts Plus Cemer	nt + 4% G	ew interval, a n, have been 8# H-40 8 iel + 2% 0	a Form 3160-4 shall b completed, and the Brd ST&C New C CaCl + 1/4# Floc	ce filed once operator has Casing. cele	
	69 sx to surf		us Cement	+ 2 /0 Ca	Ci. Flugget	u uown ai	ia bumpe	270% Ci	culated	
11/12/02			naed un 9.5	/8" casin	a Ran 10 I	Halliburtor	n centraliz	zers Lead with	800 sx	
11/12/02		of 3214' at 6:00 AM. Rigged up 9 5/8" casing. Ran 10 Halliburton centralizers. Lead with 800 sx 1/4# Flocele per sx. Tailed with 200 sx Premium Plus Cement + 1% CaCl + 1/4# Flocele per sx.								
		vn and bumped with 1180#							1 37.	
		··· -····								
See attached drilling report.					Γ	ACCEP	yen il			
							104 2.0			
14. I hereby certify that the foregoing is true and correct				Title			LF - Cris	W K WER		
Name (Printed/Typed) Natalie Krueger				-	ction Assista	ant PIT	nall	A CONTRACT DA	1	
Signature				Date						
Nat	talie &	hieger		Nove	ember 18, 20	002				
		O THIS SPACE F	OR FEDERA	L OR ST	ATE OFFICE	USE		······		
Approved by				Titl	e		Date			
Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.				ant or Off lease	ice	<u> </u>				
			ngly and willfu	lly to make	to any departm	ent or agenc	y of the Uni	ited States any false	fictitions or	
fraudulent stater	nents or representat	tes it a crime for any person knowi tions as to any matter within its juris	diction.	iny to make						

# Gruy Petroleum Management Co.

Magnum Hunter Production, Inc.

## Well History

#### November 7, 2002 Thru November 13, 2002

### **OPERATED**

#### CARLSBAD

GRUY PET	W.I. Pct BCP12.19 %W.I. Pct ACP12.19 %			
EDDY, NM	DERAL 22 CO 4		Morrow / 12,000'	
11/07/2002	1	Depth	900'FNL, 660'FEL, Sec 22, T24S, R26E 61	11011011 / 12,000
11107/2002		Progress	61	
AFE:	22288	Present Operation: Prep		
		Eddy County, New Mexic Abbott Brothers set 20" c 3 sump holes on 11/4/200 put water in reserve pit to	West Surveying on 5/8/2002 - 990' FNL & 660' FEL Sec. co. B&H Construction built location, pits & road from 10, conductor pipe at 38' FGL & cemented with ready mix - du )2. Akome, Inc. plastic lined & fenced reserve pit on 11/5, b hold down the plastic on 11/5/2002. MIRU Patterson-UT Welded flow nipple onto conductor pipe - mixed spud mu	/28/2002 to 11/1/2002. ug rat & mouse holes + /2002 - Great Basin FI Rig # 75 on
11/08/2002		Depth	445	
AFE:	22288	Progress Present Operation: NU	384 BOPs & Choke Manifold	
		drilling out 20" cond. pip- 1/20 Service rig Drill from Drop Totco @ 445' = 1/20 ST&C New Casing (449.0 219', 129' & 39' KB. Atte circ. to clear csg. Hall. ce 1/4# Flocele per sx, (Tail) 10:53 PM 11/7/02 - circu (cut off 20" conductor pip	(Spud 17 1/2" hole at 6:00 AM (CST) 11/7/2002) - no return e - pumped 80 bbl. viscous mud pill with LCM & gained m 213' to 445' TD - (Reached TD of 17 1/2" hole at 4:45P o & trip out to run 13 3/8" casing RU Csg. crew & ran 10 60') - set at 445' KB - KB to $GL = 23.00'$ - ran 5 Halliburt mpted to RU Halliburton Cement head w/o success, instal mented 13 3/8" csg. (Lead) 340 sx Prem. Plus Cement + 4 ) 150 sx Prem. Plus Cement + 2% CaCl - plug down & bu lated 69 sx cement to surface - Homer Saenz w/ the BLM be after 3 hrs. WOC) Cut off 13 3/8" casing & weld on a 1 sted between the welds to 500# for 15 mins OK	full returns WLS @ 213' = PM (CST) 11/7/2002) Circulate jts. 13 3/8" 48# H-40 8rd on centralizers: 430', 309', lled swedge & 4% Gel + 2% CaCl + imped with 270# at witnessed job. WOC -
11/09/2002		Depth Progress	864 419	
AFE:	22288	Present Operation: Drlg		
		(Verbal approval by Jim A Service rig TIH with Bit # 381' Test BOP pipe rams cement & shoe from 381'	old Test BOP blind rams, well head & 13 3/8" casing to 50 Amos with the BLM to test to 500# - BLM didn't witness # 2, Sperry Sun 8" Mud Motor, Reamer, 8" DC, Stab. & 8 & hydril to 500# with rig pump - OK Drilled cement, plu to 445' Drill from 445' to 864' (86 motor RPM & 36 rotation of & 86 motor RPM & 50 rotary RPM thereafter) - back of	test) Strap & PU BHA " DC's - tagged up @ g, float collar, ry RPM until BHA
11/10/2002		Depth 1 Progress	,620 756	
AFE:	22288	Present Operation: Drlg		
Monday, 18 M	November, 200	1,123' (87 RPM motor & RPM rotary) WLS @ 1,1'	7 RPM motor & 50 RPM rotary) WLS @ 797' = 1 1/20 D 50 RPM rotary) Service rig Drill from 1,123' to 1,249' (8 75' = 1 3/40 Drill from 1,249' to 1,566' (88 RPM motor & FEDERAL 22 COM 2	7 RPM motor & 50

		1,492 - 10 DTH HOM 1,500 10 1,020 (00 KF W HOR) & 50 KF W HORALY
11/11/2002		Depth 2,420
		Progress 800
AFE:	22288	Present Operation: Drlg
		Drill from 1,620' to 1,851' (87 RPM motor & 60 RPM rotary - 45K to 50K bit wt.) Service rig Drill from 1,851' to 2,041' (87 RPM motor & 60 RPM rotary - 45K to 50K bit wt.) WLS @ 1,967' = 1/20 Drill from 2,041' to 2,420' (87 RPM motor & 60 RPM rotary - 50K to 55K bit wt.)
11/12/2002		Depth 3,214
		Progress 794
AFE:	22288	Present Operation: Drlg
		Drill f/2420' to 2642' (87 RPM motor & 60 RPM rotary - 50K to 55K bit wt); WLS @ 2467' = 1/4 deg; drill f/2642' to 2706' (87 RPM motor & 60 RPM rotary - 55K bit wt); serv rig; drill f/2706' to 3023' (87 RPM motor & 60 RPM rotary - 55K bit wt); WLS @ 2949' = 1 deg; drill f/3023' to 3214'TD (87 RPM motor & 60 RPM rotary - 55K bit wt) - Davis Fluid Calipers ran fluid caliper while drilling from 3180' to 3195' - shows that it will take 2071.20 ft.3 (20% excess) to circulate cmt to surface with 9-5/8" casing in hole - reached TD of 12-1/4" hole at 6:00 AM, 11/12/02.
11/13/2002		Depth 3,214
		Progress 0
AFE:	22288	Present Operation: Cut Drilling Line
		Pump 80 bbl. viscous sweep & circulate Drop Totco @ $3,214' = 1/40$ & trip out standing back drill pipe RU laydown machine & POOH LD 18 - 8" DC's, stabilizer, reamer, motor & bit Service rig RU casing crew & ran 9 5/8" casing (See Casing Detail), set @ $3,214'$ KB - KB to GL = $23.00'$ - ran 10 Halliburton centralizers: $3,199'$ , 3,034', 2,855', 2,677', 2,499', 2,321', 2,142', 1,963', 1,784' & 1,605' RU & circulate to clear casing - wait on Halliburton pump truck to get to location Halliburton cemented 9 5/8" casing (Lead) 800 sx Interfill "C" + $1/4\#$ Flocele per sx, followed by (Tail) 200 sx Premium Plus Cement + $1\%$ CaCl + $1/4\#$ Flocele per sx - plug down & bumped with 1,180# at 6:24 PM 11/12/02 - circulated 81 sx cement to surface - BLM was notified - didu't witness icb ND & PLI BOP - set 9 5/8" casing slips in 75 000# - cut

surface - BLM was notified - didn't witness job ND & PU BOP - set 9 5/8" casing slips in 75,000# - cut off 9 5/8" casing - installed a 13 5/8" 3M X 11" 5M "B" Section Spool - NU BOP's & choke manifold - made repairs to accumulator Test BOP, choke manifold & associated equipment to 5,000# - OK - Paul Swartz with the BLM witnessed the test Cut drilling line & rig repair to replace kick pads on drum