

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. LC 068811-A
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

30-015-00147

July 17, 19 58

Well No. 1 is located 330 ft. from N line and 330 ft. from E line of sec. 35

NE/4, Sec. 35
(1/4 Sec. and Sec. No.)

25-S-
(Twp.)

27E
(Range)

NMPM
(Meridian)

New Mexico
(State or Territory)

Wildcat
(Field)


Eddy
(County or Subdivision)

The elevation of the derrick floor above sea level is 3100 ft. Estimated.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well drilled to a total depth of 2410' with cable tools. Hole was filled with mud up to 200 feet. 6 sax cement spotted at 200 feet and 6 sax cement spotted at surface. Balance of the hole filled with mud.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Chambers & Kennedy & J. M. C. Ritchie

Address 607 Midland National Bank Bldg.

Midland, Texas

By _____

Title Agent