

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Artesia  
Lease No. 165884-1  
Unit \_\_\_\_\_  
copy  
RECEIVED  
JAN 20 1961  
D. C. C.  
ARTESIA OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

copy 30-015-01152 September 27, 1960

Unit  
Well No. 9 Welch is located 330 ft. from S line and 330 ft. from E line of sec. 17  
SE SE 17 26S 27E N.M.P.  
( $\frac{1}{4}$  Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Welch (Delaware) Eddy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well drilled to a total depth of 2230 with cable tools. Well plugged as follows: Mud from 2230-2130; Cement 2130-2080; Mud 2080-1400; Cement 1400-1350; Mud 1350-270; Cement 220-270; Mud 270-10; Cement 0-10; Steel marker erected, pits levelled, and location is ready for inspection.

copy

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. M. C. Ritchie  
Address Box 953  
Midland, Texas  
By orig. sgd. Everett S. Smith  
Title Agent